

Report ID: 18,078,223 Version: 1 Created: 11 Jun 2018

Make:	Mitsubishi	Model:	Colt	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,003	Registration:	BQS592	Reg Expiry:	Hatchback 24 Nov 2018	Engine			
		Odometer:	-	Good No:		Oil level			
VIN:	03 Nov 2018		217,793 Kms	Service Histor	18078223	Smoke & fumes	~		<u> </u>
VIN:	JMAXSZ27A3Z000522	Next Service:		Service Histor	y: No		~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Performance	~		<u> </u>
						Noise	~		
						Cooling System			
					J	Coolant condition	~		
Kau	S S	2	S D SC SC	SS	c s sc	Performance	~		
Key: 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3						Radiator / Hoses (visual)	~		
						Transmission			
R = rust				210	E SSC	Operation	~		
PT = paint defe	ect NP				17111	Noise		~	
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		-
* = decals	S PT SC 91			The	S SC	Wheel bearings	~		
SC = stone chips						Brakes	•		1
W = significant scuffs S D SC S S S S S S S S S S S S S S S S						Performance	~		1
		Note: com				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								- f t wa	<u> </u>
Average						Tyres (lowest observed tread			-
						Left front	5 mm		
						Right front	5	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	3	3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
	on has oil leaks	6 .				Suspension performance	~		
Coolant add	ditive concentration bel	ow manufacture	s recomended level su	iggest coolant cl	hange	Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		.1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Seats Poor					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
	Average								-
Panels	5					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Concerto						Window winder FR	~		<u> </u>
General Comments					Window winder RL	~			
Transmission sounds noisy and may need attention. Car has an odour						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	<		
						CD (basic test only)	~		
						Number of keys	1		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
	-								L *
Inspected by: Roger King Date: 11 Jun 2018									
I have read a	and understood th	is condition a	uide. Name: .			Signature:			