

## **Basic Vehicle Condition Guide**

Report ID: 18,078,299


Version: 2

Created: 22 Jun 2018

Make: Model: Subaru **Body Style:** Hatchback Impreza Year: 2,007 Registration: JTJ495 Reg Expiry: 22 Oct 2018 WoF Expiry: **Odometer: Good No:** 30 May 2018 18078299 135,461 Kms VIN: **Next Service:** 7AT0GF09X16003587 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

No cargo blind

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy

Interior Commer	<u>nts</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt **Evidence of Cam Belt Replacement:** 

No

Kms:

	Pass	Fail	N/A
Engine	•		
Oil level	~		
Smoke & fumes	~		
Performance	<b>V V</b>		
Noise	~		
Cooling System	•	•	
Coolant condition	~		
Performance	<b>v</b>		
Radiator / Hoses (visual)	~		
Transmission		•	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		1	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	4		mm
Right front	4		mm
Left rear	4		mm
Right rear	4		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories		ı	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)			
CD (basic test only)	<b>'</b>		1
CD (basic test offiy)	V		
Number of keys	<b>v</b> 1		
<u> </u>	-		
Number of keys	-	·	

I have read and understood this condition guide.

Stuart Melbourne

Name: .....

Signature: .....

22 Jun 2018

1

Reversing camera