

Report ID: 18,078,776 Version: 1 08 Jun 2018 Created:

Make:	Subaru	Model:	Outback	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	HLG93	Reg Expiry:	13 Aug 2018	Engine			L
WoF Expiry:	21 Aug 2018	Odometer:	105,353 Kms	Good No:	18078776	Oil level	~		
VIN:	JF2BRMKC5EG064785	Next Service:	112500	Service Histor	y: Yes	Smoke & fumes	~		
No. The						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	. Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	lis can be analiged to		narge.	Coolant condition	~		
	S SC		S D		S D	Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	sw AR			10	Ell s	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					S	Clutch			~
P = pin dent	sc de				74II <u>L</u>	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = Significan	S P W	\sim	S D S D			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
					Left front	8	3	mm	
						Right front	8 mm		mm
						Left rear	8	3	mm
Conditions During Body Inspection: Dry						Right rear	8 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering performance							~		
Shock ab							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Drivers de	nt, cut and left re	ear scratches			Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	iu ý					Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: John Lindsay Date: 08 Jun 2018									
Inspected by. Joint Enrosay Date: 06 Juli 2018									

I have read and understood this condition guide.

Name:

Signature: