

Report ID: 18,078,782 Version: 3 15 Jun 2018 Created:

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,004	Registration:	JQM40	Reg Expiry:	09 Jul 2018	Engine			
WoF Expiry:	05 Feb 2019	Odometer:	79,952 Kms	Good No:	18078782	Oil level	~		
VIN:	7AT0C12HX16309400	Next Service:	81785	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	lis can be arranged to		narge.	Coolant condition	~		
			S			Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	sc pp			10		Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	sc de				241 <u>1</u> 5	CV joints	~		
* = decals SC SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
					S	Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
LR window fail at door						Tyres (lowest observed tread depth of tyres)			
						Left front	3 mm		mm
						Right front	Ĩ	2	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 15 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: