

I have read and understood this condition guide.

Report ID: 18,079,263 Version: 2 05 Jul 2018 Created:

Signature:

| Make: | Ford | Model: | Transit | Body Style: | Van | | Pass | Fail | N/A |
|--|--------------------|----------------------|------------------------|--------------------|----------------------|--|------|------|-----|
| Year: | 2,011 | Registration: | FYC771 | Reg Expiry: | 06 Oct 2018 | Engine | | | |
| WoF Expiry: | 22 Jan 2019 | Odometer: | 151,708 Kms | Good No: | 18079263 | Oil level | ~ | | |
| VIN: | WF0XXXTTFXAP11245 | Next Service: | 178800 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | | ~ | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | SP | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust SC D D | | | | | | Operation | ~ | | |
| PT = paint defect | | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | ~ | | |
| P = pin dent | HIP | | | | ᅰ | CV joints | | | ~ |
| *= decals SC 99 | | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S P S S | | | | | | Performance | ~ | | |
| Body Inc | postion Commonts | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | es) |
| RR tail light cracked | | | | | | | | | mm |
| | | | | | | Right front | |) | mm |
| | | | | | | Left rear | | 1 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 4 mm | | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | 1 | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 | | 1 |
| L | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| Engine kno | cking noise | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Bobby Zhong Date: 05 Jul 2018 | | | | | | | | | |
| | | | | | | | | | |

Name: