

## **Basic Vehicle Condition Guide**


Report ID: 18,079,715

Version:

Make: Model: Hilux **Body Style:** Utility Toyota Year: 2,012 Registration: GPS760 Reg Expiry: 26 Aug 2018 WoF Expiry: **Odometer: Good No:** 12 Jan 2019 18079715 88,792 Kms VIN: MR0EZ12G904156382 Next Service: **Service History:** Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Good	

## **General Comments**

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt **Evidence of Cam Belt Replacement:** 

No

Kms:

Inspected by:	Stuart Melbourne
---------------	------------------

Create	Created: 12		Jun 2018	
	Pass	Fail	N/A	
Engine				
Oil level	<b>'</b>			
Smoke & fumes	\( \times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	<b>V</b>			
Performance	<i>V</i>			
Radiator / Hoses (visual)	~			
Transmission				
Operation	<b>V</b>			
Noise	<i>V V</i>			
Clutch	•			
CV joints				
Wheel bearings			·	
Brakes	V			
Performance	•			
Hand Brake	· · · ·		Ļ	
Tyres (lowest observed tread	depth	of tyre	-	
Left front	9		mm	
Right front	9		mm	
Left rear	4	1	mm	
Right rear	9		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	V V			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	\( \times \)			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1	<u> </u>		
Central locking	·			
Remote locking	~			
Sat. Nav. (basic test only)			./	
Reversing camera			.,	
eversing cumera				

Date: 12 Jun 2018

I have read and understood this condition guide. Name: ..... Signature: .....