

Report ID: 18,079,990 Version: 1 24 Jun 2018 Created:

Make:	Subaru	Model:	Outback	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,009	<b>Registration:</b>	FBZ962	<b>Reg Expiry:</b>	30 Aug 2018	Engine	1	I		
WoF Expiry:	20 May 2019	Odometer:	170,656 Kms	Good No:	18079990	Oil level	~			
VIN:	7A8GF160709004806	Next Service:	179748	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and ti	lis can be analiged to		inarge.	Coolant condition	~			
			S		S	Performance	~			
<b>Key:</b> S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~			
D = dent						Transmission				
R = rust	sc PR			10	HI IS	Operation	~			
PT = paint def	ect NP					Noise	~			
C = crack				$\square$	SC	Clutch			~	
P = pin dent	sc de				~HHL	CV joints	~			
* = decals SC = stone chi		10		10	EP S	Wheel bearings	~			
W = significant scuffs						Brakes				
			D		S	Performance	~			
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
					Left front	<u>[</u>	5	mm		
						Right front	5	5	mm	
						Left rear		5	mm	
Conditions During Body Inspection: Wet						Right rear	5 mm		mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
Interior Comments Average						Electrical / Accessories				
Seats	Avelage					Head lights	~			
Carpets	Good					Tail lights	~			
	Good					Indicators	~			
Panels	Guu					Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	~			
	-					Window winder FL	~			
General	omments					Window winder FR	~			
General Comments Audio screen weak						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
Engine Ti	ming Mechanism	Camebal				Remote locking	~			
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 115.665						Sat. Nav. (basic test only)			~	
	or cam beit nepiac	спісні, ү	es	NIII3.	5,665	Reversing camera			~	
Inspecte	Inspected by: Xinghui Lin Date: 24 Jun 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....