

Report ID: 18,081,218 Version: 1 19 Jul 2018 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,006	Registration:	HJJ823	Reg Expiry:	26 Jul 2018	Engine			
WoF Expiry:	11 Jun 2018	Odometer:	166,689 Kms	Good No:	18081218	Oil level		~	
VIN:	7AT0C13JX14305546	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	V		
Key:	SW	-0	SP			Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust S PT S W						Transmission			
						Operation	~		
PT = paint defe	ect NP			$\left(\left \left(\right) \right\rangle \right)$	7011	Noise	r		
C = crack						Clutch			~
P = pin dent	HE				74116	CV joints	~		
* = decals	ssc 916					Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs W S W						Performance	~		
Body Incr	position Commonts	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Crack front careen Spare wheel loose						Tyres (lowest observed tread depth of tyres)			es)
Crack front screen.Spare wheel loose.						Left front 6.5 m			
						Right front		.5	mm
						Left rear		.5	mm
Conditions During Body Inspection: Drv						Right rear			mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
FWD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ord Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments					Window winder RL	~			
Washer not working.Engine check light on. Low battery voltage.Engine oil level on low low mark.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
[•								-
Inspected by: Eddie Marsters Date: 19 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: