

Report ID: 18,082,416 Version: 2 19 Jun 2018 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,005	Registration:	GSP43	Reg Expiry:	04 Nov 2018	Engine	1		I
WoF Expiry:	,	Odometer:	209,159 Kms	Good No:	18082416	Oil level	~		
VIN:	7AT0C139X13400793	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I		1 B AL	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	sc	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust				10	JHIN	Noise	~		
PT = paint defe C = crack	ect M			+		Clutch	~		
P = pin dent	Ho	KI			JIII —				~
* = decals	sc pp			SI		CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs SC SC SC W SC W S W						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	3	.0	mm
						Right front	3	3.0 n	
						Left rear	2.0 m		mm
Conditions During Body Inspection: Wet						Right rear	2.0 mm		mm
						Spare	Spare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension	uspension		
Both iner cv	v boots split					Suspension performance	~		
						Steering performance		~	
						Shock absorbers	V		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	V		
	Good					Tail lights	V		
Carpets	dood					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	·					Wipers (front & rear)	~		
Dashboa	rd panel brok	ken				Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
Steering shaking at low speed						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			
						-	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Tir	ming Mechanism:	Timina	Thain			Remote locking	~		
						Sat. Nav. (basic test only)			~
			lot Applicable	14115.		Reversing camera			~
Inspected	d by: Dion Mair					Date: 12 Jun 20	18		

I have read and understood this condition guide.

Name:

Signature: