

Report ID: 18,083,122 Version: 2 Created: 08 Aug 2018

Make:	BMW	Model:	1 Series	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,008	Registration:	HSN65	Reg Expiry:	10 Feb 2019	Engine			1
WoF Expiry:	26 Jun 2019	Odometer:	72,478 Kms	Good No:	18083122	Oil level	~		
VIN:	WBAUD32070PF46872	Next Service:	73,000	Service Histor	y: No	Smoke & fumes	~		
	_					Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
	S				DW	Performance	~		
Key:	B	-0	S S			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent * = decals						CV joints			~
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts P SC S S						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Rear badge missing						Tyres (lowest observed tread depth of tyres)			
Glove box lock missing						Left front 3		3	mm
						Right front	:	2	mm
						Left rear	(5	mm
Conditions During Body Inspection: Dry						Right rear 6		5	mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil le	eak					Suspension performance	~		
S						Steering performance	~		
	Shock absorbers	~							
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Correcto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights		~	
Dashh	Average					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Mathew Varghese Date: 08 Aug 2018									
Inspected by. Wathew Vargnese Date: U8 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: