

Report ID: 18,083,271 Version: б 01 Oct 2018 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2007	<b>Registration:</b>	FLL935	<b>Reg Expiry:</b>	11 Feb 2019	Engine		1	
WoF Expiry:	03 Jul 2019	Odometer:	237,191 Kms	Good No:	18083271	Oil level	~		
VIN:	VSKCVND40A0143221	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged to	r an additional o	narge.	Coolant condition	~		
			S		S	Performance	V		
Key:		=		500-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			
R = rust	s c sc			10	HILP	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch	~		
P = pin dent	DSC DE				74II.L	CV joints	~		
* = decals		10		10	ED SP	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
					S	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Right wing mirror cover cracked						Tyres (lowest observed tread depth of tyres)			
						Left front	9	.0	mm
						Right front	9	.0	mm
						Left rear	10	0.0	mm
Conditions During Body Inspection: Dry						Right rear	10	0.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonte						Operation	~		
Interior Comments						Electrical / Accessories		1	
Seats	1001					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Ganaral	<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism:	Timing				Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Xinghui Lin Date: 27 Sep 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....