

Report ID: 18,083,612 Version: 3 20 Jun 2018 Created:

Make:	Volkswagen	Model:	Touareg	Body Style:	SUV		Pass	Fail	N/A
Year:	2,008	Registration:	KNC1	Reg Expiry:	02 May 2019	Engine			L
WoF Expiry:	2,000 08 Jun 2019	Odometer:	128,037 Kms	Good No:	18083612	Oil level	~		
VIN:	WVGZZZ7LZ8D01430			Service Histor		Smoke & fumes	~		
	,;;;]					Performance	~		
	port is not a warranty		6	Dant I	have all states	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	s sc w	-0	SW SW		S W	Radiator / Hoses (visual)	~		<u> </u>
S = scratch	STE	A CO	$\overline{\neg}$		X	Transmission	•		
D=dent B= mut						Operation	~		
R = rust 3.3C MP						Noise	~		
C = crack	ect			+	S SC W	Clutch			~
P = pin dent	Ho				JUII ——	CV joints	~		
* = decals S PT SC W P P						Wheel bearings			<u> </u>
SC = stone chips						Wheel bearings			
W = significant scuffs SW SW SW SW						Performance	~		
		Note: com				Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram									
Paint worn on bonnet. Stone chips in windscreen. Inside edge wear on right rear tyre.						Tyres (lowest observed tread depth of tyres) Left front 7.3			
								.3	mm
						Right front		.0	mm
						Left rear	4.2 mn		
Conditions During Body Inspection: Dry						Right rear	4.6 mn		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
			<u>an comments</u>			Suspension		1	
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	0000					Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		<u> </u>
	Good					Indicators	~		<u> </u>
Panels	Guu					Dashboard warning lights	~		<u> </u>
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Concret	Commonts					Window winder FR	~		<u> </u>
General Comments					Window winder RL	~		<u> </u>	
Central locking not working on right rear door. Plastic engine covers missing off top of engine. Had after market radio fitted, so controls on steering wheel don't work. Both right & left electric wing mirrors not moving in any direction with switch. ###Correct kms are 120,841kms###						Window winder RR	~		
						Rear view mirrors		~	
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking		~	
En aliz - T'	ming Mashauting	<u> </u>	- ·			Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecte	d by: Jason Young					Date: 12 Jun 20	18		

I have read and understood this condition guide.

Name:

Signature: