

Basic Vehicle Condition Guide

Report ID: 18,084,709


Version:

Created: 07 Aug 2018

Make: Model: Subaru Outback **Body Style:** SUV Year: 2,014 Registration: HDM53 Reg Expiry: 24 Aug 2018 WoF Expiry: **Odometer:** 12 Feb 2019 **Good No:** 18084709 147,136 Kms VIN: JF2BRMKC5EG061362 **Next Service:** 129500 **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left rear reflector broken

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Only one remote key working

Interior Comments			
Seats	Hole in drivers seat, stains on rear seat		
Carpets	Average		
Panels	Dents in drivers door panel		
Dashboard	Average		

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System	•	•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	d depth	of tyre	es)
Left front	6	 5	mm
Right front		5	mm
Left rear	6		mm
Right rear	5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater	<u> </u>		1
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	·		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking			~
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera	<i>y</i>		
eversing curriera			

I have read and understood this condition guide.

John Lindsay

Name:

Signature:

07 Aug 2018

Date: