

Basic Vehicle Condition Guide

Report ID: 18,086,563

Version:


Created: 06 Jul 2018

Make: Model: Suzuki Splash **Body Style:** Hatchback

Year: 2,009 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 11 Jun 2019 18086563 58,975 Kms VIN: TSMEXB32S00297119 **Next Service: Service History:** 69,000

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Wet

Timing Chain

Evidence of Cam Belt Replacement:

Engine Timing Mechanism:

Not Applicable

Kms:

Name:

			<u> </u>		
Inspected by:	Murray Craig			Date:	06 Jul 2018

	Pass	Fail	N/A
Engine	. 433	, un	11/7
Oil level	~		
Smoke & fumes	~		
Performance	V		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			V
CV joints	~		
Wheel bearings	~		
Brakes	I	<u> </u>	1
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l d depth	of tyre	es)
Left front		3	mm
Right front		3	mm
Left rear		3	mm
Right rear	8	3	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories		ı	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Daviansia a samana	· .		
Reversing camera	'		

Signature: