

## **Basic Vehicle Condition Guide**

Report ID: 18,086,688

Pass

Version:

Created: 02 Aug 2018

Fail

N/A

Make: Subaru Model: Impreza Body Style: Hatchback


 Year:
 2,007
 Registration:
 Reg Expiry:

 WoF Expiry:
 11 Jun 2019
 Odometer:
 91,832 Kms
 Good No:
 18086688

 VIN:
 7AT0GF09X18003473
 Next Service:
 101,803kms
 Service History:
 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Wet

**Conditions During Body Inspection:** 

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

**General Comments** 

Nice tidy AWD hatch.

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

**Daryll Timms** 

Evidence of Cam Belt Replacement: Y

Yes Kms: 63,000

Name: .....

Engine			
Oil level	~		
Smoke & fumes	~		
Performance	<b>v</b>		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	<b>v</b>		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front		7	mm
Right front		7	mm
Left rear			mm
Right rear	7 mm		
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	\( \times \)		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	\( \times \)		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

02 Aug 2018

Signature: .....

I have read and	understood this	condition guide.