

Report ID: 18,087,335 Version: 1 Created: 07 Aug 2018

Make:	Holden	Model:	Barina	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,016	Registration:	KEN943	Reg Expiry:	14 Jul 2018	Engine			L
WoF Expiry:	_,• • •	Odometer:	50,306 Kms	Good No:	18087335	Oil level	~		
VIN:	KL3TA48E9HB033282	Next Service:	50,000 14115	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	haan diamantlad ar	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc			The		Operation	~		
R = rust PT = paint def	ect NP			$\prod$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		-
* = decals	sc 916			The	<b>HIP</b>	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	of tyre	<u> </u>
								mm	
						Right front		5	mm
						Left rear		5	mm
Conditio	as During Pody Inc	naction	14/			Right rear			mm
Conditions During Body Inspection: Wet						Spare	6 mm Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Tidy	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	Ird Good					Window winder FL	~		
	1					Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	2 V		
			Wet			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac		lo	Kms:		Reversing camera	~		<u> </u>
	-						-		
Inspected by: Stuart Melbourne Date: 07 Aug 2018									
I have read and understood this condition guide. Name:									