

Report ID: 18,088,464 Version: 4 Created: 25 Oct 2018

Make:	Volkswagen	Model:	Crafter	Body Style:	Van		Pass	Fail	N/A
Year:	2013	Registration:	HCF455	Reg Expiry:	13 Jul 2018	Engine	1	I	1
WoF Expiry:	24 Oct 2019	Odometer:	95,024 Kms	Good No:	18088464	Oil level	~		
VIN:	WV1ZZZ2EZE6004808	Next Service:	110000	Service Histor		Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Darts have not been dismontiad as						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	SP SP			Radiator / Hoses (visual)	~		
S = scratch						Transmission			<u> </u>
D = dent						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch	~		
P = pin dent						CV joints	~		
* = decals SC QQ						Wheel bearings			
SC = stone chips						Brakes	~		
W = significant scuffs S D D						Performance			
Natu como defecte ⁰ blamichos may not be displayed in the diagram							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Left rear taillight cracked						Tyres (lowest observed tread depth of tyres)			
Left rear bumper reflector broken						Left front	8 mm		-
						Right front		3	mm
						Left rear		7 mm	
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder Carnage & onder Bonnet inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Stains and hole drivers seat						Electrical / Accessories			
Seats	stains and	noie unvers seat	L			Head lights	~		
Carpets	Average					Tail lights		~	
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dealthead	Average					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
	-					Window winder FR	~		
General (<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
с									
Inspected by: John Lindsay Date: 25 Oct 2018									
I have read and understood this condition guide. Name:									