

## **Basic Vehicle Condition Guide**

Report ID: 18,088,884

**Pass** 

1

V

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition

Created: 10 Aug 2018

Fail

N/A

1

mm

mm

mm

mm

4.0

6.0

6.0

1

/


/

Yes

Make: Model: Golf **Body Style:** Hatchback Volkswagen Year: Registration: **Reg Expiry:** 2,007 JHG23 30 Jun 2018 **WoF Expiry: Odometer: Good No:** 18088884 21 Dec 2018 128,215 Kms WVWZZZ1KZ7U01157 Next Service: VIN: **Service History:** 136708 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** Yes

**Bobby Zhong** 

I have read and understood this condition guide.

Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking

Kms: 117,359	Sat. Nav. (basic test only)  Reversing camera	\( \times \)		
Date: 28 Jun 2018				
Name:	Signature:			