

Report ID: 18,089,925 Version: 1 14 Aug 2018 Created:

Make:	Mazda	Model:	Premacy	Body Style:	SUV		Pass	Fail	N/A
Year:	2,008	Registration:		Reg Expiry:		Engine	I	1	L
WoF Expiry:		Odometer:	95,609 Kms	Good No:	18089925	Oil level	~		
VIN:	7AT0C133X18312998	Next Service:	105536	Service Histor		Smoke & fumes	~		<u> </u>
						Performance	~		<u> </u>
	port is not a warranty		for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	iical inspection prior to	purchase and t	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	SD P	-M-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s sc			715	HIL	Operation	~		
PT = paint defe	ect NP			$\left(\right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIS				74114	CV joints	~		
* = decals	- Alt			-No-	AD S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant	s w	- NO	S S D		SC	Performance	~		
Pedular	action Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
	pection Comments					Tyres (lowest observed tread	d depth	of tyre	L 2S)
									mm
						Right front		5 5	mm
						Left rear		3	mm
Conditions During Body Inspection: Drv						Right rear		, 7	mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Marks on s	seats				Head lights	~		
	Markson	carpots				Tail lights	~		
Carpets	Marks on o	carpers				Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
	A					Wipers (front & rear)	~		
Dashboa	ard Average					Window winder FL	~		<u> </u>
	I					Window winder FR	~		<u> </u>
General Comments					Window winder RL	~		<u> </u>	
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	· ·		
						Remote locking	~		<u> </u>
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L							1	l	L
Inspected by: John Lindsay Date: 14 Aug 2018									

I have read and understood this condition guide.

Name: