

Report ID: 52,049 Version: 1 Created: 29 Jun 2018

Make:	Renault	Model:	Megane II	Body Style:	Hatchback			Pass	Fail	N/A	
Year:	2,006	Registration:			Engine						
WoF Expiry:	29 Jul 2018	Odometer:	188,378 Kms	Good No:	18091907		Dil level	~			
VIN:	VF1BM1B0H50631791	Next Service:	Just serviced	Service Histor	' y: No	S	moke & fumes	~			
						i P	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						N	loise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Co	Cooling System				
							Coolant condition	~			
						I P	Performance	~			
Key:	SC S	-0	S S	-(0)-	s	R	adiator / Hoses (visual)	~			
S = scratch D = dent R = rust PT = paint defect						Tra	Transmission				
							Dperation	~			
						N	loise	~			
							lutch	~			
P = pin dent							V joints	~		<u> </u>	
* = decals SC S 9 9 S						V	Vheel bearings	~			
SC = stone chips						Brakes					
W = significant scuffs SC S D S S D S						Performance 🖌					
Note: come defecte & blamichec may not be dienlayed in the diagram							land Brake	~		<u> </u>	
Body Inspection Comments							Tyres (lowest observed tread depth of tyres)				
All electric window switches stick A/C / heater fans not working						I⊢́	Left front 4.0 mi				
							light front			mm	
										mm	
Conditions During Rody Inspection:						ı⊢	light rear	3.0		mm	
Conditions During Body Inspection: Dry											
Under Carriage & Under Bonnet Inspection Comments							Spare Yes Suspension				
							spension performance	~			
							teering performance	v v			
							hock absorbers	v v			
							r Conditioning / Heater	V			
							Operation			<u> </u>	
Interior Comments									~		
Casta	2)/972/09						lead lights			T	
Seats							-	V		-	
Carpets	average					⊢	ail lights	v			
	average						ndicators	/			
Panels	areage						Dashboard warning lights	/			
Dashboa	rd average						Vipers (front & rear)	~			
							Vindow winder FL		~		
General	omments						Vindow winder FR		~	<u> </u>	
General Comments Clutch worn							Vindow winder RL		~	<u> </u>	
							Vindow winder RR		~		
						⊢	lear view mirrors	~		<u> </u>	
							adio (basic test only)	~			
							D (basic test only)	~			
						. ⊢	lumber of keys	1			
Road Conditions During Test Drive: Dry							Central locking	~		<u> </u>	
Engine Timing Mechanism:							lemote locking			~	
Engine Timing Mechanism: Cambelt						S	at. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: No Kms:						R	leversing camera			~	
Inspected by: D M Auots							Date: 20 Jun 2018				
I have read and understood this condition guide. Name:											

Name: