

Basic Vehicle Condition Guide

Report ID: 18,092,699


Version: 1

Created: 16 Jul 2018

Make: Model: Nissan Murano **Body Style:** SUV Year: 2,005 Registration: HQQ144 Reg Expiry: 01 Jul 2018 **WoF Expiry: Odometer:** 12 Jul 2019 **Good No:** 18092699 142,792 Kms VIN: 7AT0DH74X14003779 Next Service: **Service History:** 152000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: lan Dunn Date: 21 Jun 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	V V		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	'		
Clutch			~
CV joints	>		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	7.6		mm
Right front	7	.5	mm
Left rear	6.2		mm
Right rear	6.1		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		!	•
Operation	~		
Electrical / Accessories			
Head lights	1		
Tail lights	~		
Indicators			
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	\(\times \)		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)		~	
CD (basic test only)		~	
Number of keys	1	<u> </u>	1
Central locking	_		
Remote locking	_		
Sat. Nav. (basic test only)			~
Reversing camera	~		
3			

Signature: