

Report ID: 18,092,858 Version: 1 20 Jun 2018 Created:

Make:	Hyundai	Model:	Sonata	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,014	Registration:	LJB99	Reg Expiry:	30 Sep 2018	Engine			L
WoF Expiry:	2,014 22 Dec 2018	Odometer:	42,829 Kms	Good No:	18092858	Oil level	~		
VIN:	KMHE341BMFA08142	Next Service:	52500	Service Histor		Smoke & fumes	~		
			52500			Performance	~		
	port is not a warranty		с I I	<b>D</b>		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	S SC	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			1n-		Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	s sc PIP			AL.	EIIR	Wheel bearings	~		<u> </u>
SC = stone chips						Brakes			
W = significant scuffs S D SC						Performance			<u> </u>
Notes come defecte 8 blamiches may not be displayed in the disparam						Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								ofture	
						Tyres (lowest observed tread depth of tyres)			
						Left front		7	mm
						Right front	7		mm
						Left rear	6	-	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	mermspectic	<u>on comments</u>			Suspension			<del></del>
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			T
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
						Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	2		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
							10		
Inspected by: Donovan Matara Date: 20 Jun 2018									
I have read and understood this condition guide. Name:									