

Turners Certified Imports 50 Point Check

Report ID: 18,092,929

Version: 2

• Not applicable for this vehicle

Date: 05 Oct 2018

Signature:

Created: 05 Oct 2018

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED ad ac	iagnostic testing undertaken. The vel ccredited inspection agency and been	hicle has undergone a thorough co test driven up to 50km/h from cold.	mpliance check by an NZTA
Make: Nissan Model: Skyline Year: 2007 Under Carriage & Under I	Body Style: Sedan Odometer: 115,731 Kms VIN: 7AT0DH12X18203870 Bonnet Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good	
General Comments		Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive:	Timing Chain Not Applicable Wet
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 5 mm
Head lights	Noise	Smoke & fumes	Right front 5 mm
Tail lights	Clutch	Performance	Left rear 4 mm
Indicators	CV joints •	Noise	Right rear 4 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail

2

Inspected by: Jason Law

Number of keys

Reversing camera