

Report ID: 18,093,442 Version: 1 22 Jun 2018 Created:

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Year:	2,008	Registration:	ERB986	Reg Expiry:	30 Oct 2018	Engine	I		L
WoF Expiry:	04 Jul 2018	Odometer:	175,111 Kms	Good No:	18093442	Oil level	~		
VIN:	KMHJN81BR9U962063	Next Service:	185000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	anation is maada	for one and miles as	Danta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	P SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			I
D = dent S = suct S SC D D F S						Operation	~		
R = rust PT = paint defe				\int	JHIH	Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		-
* = decals	SDCSC 916			- NL	S SC	Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs S SC S P SC S SC S P SC						Performance	~		
		Note: som		may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	of tyre	
					Left front			 	
						Right front			mm
						Left rear		7	mm
						Right rear			
Conditions During Body Inspection: Dry							3 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	j					Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Conditioning / He							V		I
						Operation	~		
Interior Comments						Electrical / Accessories			
						Head lights			
Seats						Tail lights	V 		
Carpets	Average						~ ~		
	sun glasse	s holder missing	from the roof ,						
Panels		5				Dashboard warning lights Wipers (front & rear)	v		
Dashboa	rd Average					Window winder FL	~ ~		
						Window winder FL			
General Comments						Window winder FR	~		
							~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Tir	ming Mechanism:	Cambelt				Remote locking	~		
						Sat. Nav. (basic test only)			~
Lvidence		спепс. ү	es	11115. 91	,000	Reversing camera			~
Inspected by: Donovan Matara Date: 22 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: