

Report ID: 18,095,413 Version: 1 16 Jul 2018 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Sedan			Pass	Fail	N/A	
Year:	2,010	Registration: FMG585 Reg Expiry: 04 Aug 2018				Engine	Engine				
WoF Expiry:	14 Mar 2019	Odometer:	62,382 Kms Good No: 18095413			Oil le	vel	~			
VIN:	WF0DXXGBBDAJ0631	Next Service:	Just serviced	Service Histor	<b>y:</b> No	Smok	e & fumes	~			
						Perfo	rmance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise		~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System					
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coola	int condition	~			
					s	Perfo	rmance	~			
Key:	SC	-0		-01-		Radia	tor / Hoses (visual)	~			
S = scratch						Transn	Transmission				
D = dent R = rust SC D R W						Opera	Operation				
PT = paint defe	ect NP	r I		$\left( \left  \left( \right) \right\rangle \right)$	701h	Noise		~			
C = crack						Clutc	h			~	
P = pin dent	HIP				74116	CV jo	ints	~			
* = decals	sc 916			10	ELC'S	Whee	el bearings	~			
SC = stone chips W = significant scuffs						Brakes					
						Perfo	Performance				
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand	Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				es)	
						Left f	Left front 2 r			mm	
						Right	Right front		2 m		
						Left r	Left rear		2 mm		
Conditions During Body Inspection: Dry						Right	Right rear		2 mm		
						Spare	Spare		Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension					
						Suspe	ension performance	~			
						Steer	ing performance	~			
						Shoc	Shock absorbers 🖌				
						Air Conditioning / Heater					
						Operation 🖌					
Interior Comments						Electrical / Accessories					
Seats	Good					Head	lights	<			
Carnete	Good					Tail li	ghts	~			
Carpets						Indica	ators	~			
Panels	Good					Dash	board warning lights	~			
Dashboa	Good					Wipe	rs (front & rear)	۲			
	iiu					Wind	ow winder FL	~			
						Wind	ow winder FR	~			
General C	<u>Comments</u>					Wind	ow winder RL	~			
						Wind	ow winder RR	~			
						Rear	view mirrors	~			
						Radio	(basic test only)	~			
						CD (b	asic test only)	~			
						Number of keys 2					
Road Conditions During Test Drive: Dry						Centr	al locking	~			
	mina Mashautau	<u> </u>					ote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. N	lav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Rever	rsing camera			~	
Inspected by: Dion Mair Date: 19 Jun 2018											
	a sy. Dion man						Dute. 19 Juli 20				

I have read and understood this condition guide.

Name: .....

Signature: .....