

Report ID: 18,095,421 Version: 2 19 Jun 2018 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:	HMJ326	Reg Expiry:	13 Oct 2018	Engine			
WoF Expiry:	30 Apr 2019	Odometer:	123,632 Kms	Good No:	18095421	Oil level	~		
VIN:	7AT0GF09X14026373		138679	Service Histor		Smoke & fumes	~		
	7/1100105/110205/5		150075			Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
		_				Performance	~		
Key:		-0	P SC P SC		S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent									
R = rust				10	SAIK	Operation	~		
PT = paint defect						Noise	~		
C = crack P = pin dent						Clutch			~
* = decals PT PT PT						CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Bonnet painted not a good job,missing reflectors out of rear bumper ,						Tyres (lowest observed tread depth of tyres)			es)
						Left front	4 mm		
						Right front	4	ł	mm
						Left rear	4	ł	mm
Conditions During Body Inspection: Wet						Right rear	2	1	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	<		
Interior Comments						Electrical / Accessories			
Seats	cigarette h	oles front seats,				Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
							1		I
Inspected by: Donovan Matara Date: 19 Jun 2018									
I have read and understood this condition guide. Name:									