

Report ID: 18,095,432 Version: 1 Created: 31 Jul 2018

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A	
Year:	2,008	Registration:	EHU861	Reg Expiry:	26 Jan 2019	Engine			·	
WoF Expiry:	22 Aug 2018	Odometer:	229,377 Kms	Good No:	18095432	Oil level	~			
VIN:	VSKCVND40A0259068	Next Service:	236500	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~			
	SC				C D C C	Performance	~			
Key:	ISC (C	-0	S P SC S P SC		S P SC	Radiator / Hoses (visual)	~			
S = scratch D = dent R = rust PT = paint defect C = crack						Transmission				
						Operation	~			
						Noise	~			
						Clutch	~			
P = pin dent						CV joints	~			
s D SC						Wheel bearings	~			
SC = stone chips						Brakes	Brakes			
W = significant scuffs S SC S P SC S S SC						Performance	~			
Body Insr	ection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres)				
winter storie emps in the windscreen,						Left front 7 m			mm	
						Right front	5	7	mm	
						Left rear	e	5	mm	
Conditions During Body Inspection: Dry						Right rear	6 mm		mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	1			
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	drivers sea	drivers seat ripped, wear and tear ,				Head lights	~			
	Average			Tail lights	~					
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
	-		-			Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspected by: Donovan Matara Date: 31 Jul 2018										

I have read and understood this condition guide.

Name:

Signature: