

Report ID: 18,095,445 Version: 2 Created: 04 Jul 2018

Make:	Honda	Model:	Odyssey	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,004	Registration:	JPM580	Reg Expiry:	21 Jul 2018	Engine	1		1
WoF Expiry:	26 Feb 2019	Odometer:	100,353 Kms	Good No:	18095445	Oil level	~		
VIN:	7AT08G61X15052508	Next Service:	nil	Service Histor	y: Yes	Smoke & fumes	~		
_						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S PT P W	-0	S S	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent B = rust SDPTC SPTC						Operation	~		
R = rust PT = paint defe				\int		Noise	~		
C = crack				+		Clutch			~
P = pin dent					세비	CV joints	~		-
* = decals	ssc 916			- AL	ETTPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance V			1
Note: come defects % blomiches may not be displayed in the diagram						Hand Brake	~		
body inspection comments							•		
Both headlights lens dirty.						Left front	Tyres (lowest observed tread depth of tyre		
							3		mm
						Right front Left rear	3		mm mm
								4	
Conditions During Body Inspection: Dry						Right rear	4	4 mr	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
FWD. Engine fluid leak. Left front tyre cord showing.						Suspension			
FWD. Engin	ie huid leak. Left front ty	re cora snowing].			Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
	Good					Electrical / Accessories	1		1
Seats	0000					Head lights	~		<u> </u>
Carpets	Good					Tail lights		~	
curpets	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashbud						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u> Left hand taillight n number plate lights not working.Radio static noise.						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		>	
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		1
						L			
Inspected by: Eddie Marsters Date: 04 Jul 2018									
I have read	and understood th	is condition c	uide. Name:			Signature:			