

Report ID: 18,095,704 Version: 1 21 Jun 2018 Created:

Make: Hyundai Model: 140 Body Style: Wagon	Pass	Fail N/A
Year:     2,015     Registration:     JCQ515     Reg Expiry:     28 Aug 2018     Engine		
WoF Expiry:         29 May 2018         Odometer:         110,237 Kms         Good No:         18095704         Oil level	✓	
VIN:     KMHLB81UMFU09473     Next Service: 117000     Service History: No     Smoke & fu		
Performance		
Note: This report is not a warranty		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling Syst	-	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		
Performance		
	oses (visual)	
S = scratch		
D=dent	· · · · · · · · · · · · · · · · · · ·	
	V	
PT = paint defect C = crack	<b>v</b>	· ·
P = pin dent	· ·	
* = decals SC 999 Wheel bear		
SC = stone chips	ings 🖌	
W = significant scuffs W P W D Performance		
Note: come defects ? blemiches may not be dienlayed in the diagram	•	
Body inspection Comments	•	
	Tyres (lowest observed tread depth of tyres)	
		4 mm
Right front		4 mm
Left rear		7 mm
Conditions During Body Inspection: Dry Right rear		7 mm
Under Carriage & Under Bonnet Inspection Comments Suspension	1 105	
	performance 🖌	
Steering pe		
Shock abso	•	
Air Condition	ning / Heater	
Interior Comments	~	
	Electrical / Accessories	
Seats Head lights	~	
Carpets Good Tail lights	~	
Indicators	~	
	warning lights 🖌	
Dashboard Good Wipers (from	nt & rear) 🖌	
Window wi	nder FL 🖌	
Window wit	nder FR 🖌	
General Comments Window wi	nder RL 🖌	
Window wit	nder RR 🖌	
Rear view m	nirrors 🖌	
Radio (basic	test only) 🖌	
CD (basic te	st only) 🖌	
Number of	keys 2	
Road Conditions During Test Drive: Wet Central lock	ing 🖌	
Remote loc	king 🖌	
	asic test only)	~
Evidence of Cam Belt Replacement: Not Applicable Kms:	amera 🖌	
Inspected by: John Lindsay Date: 21 Jun 2018		
Inspected by: John Lindsay Da	te: 21 Jun 2018	

I have read and understood this condition guide.

Name: .....

Signature: .....