

Report ID: 18,095,715 Version: 1 21 Jun 2018 Created:

Make:	Skoda	Model:	Superb	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,014	Registration:	HPP21	Reg Expiry:	21 Aug 2018	Engine			L
WoF Expiry:	08 Sep 2018	Odometer:	138,757 Kms	Good No:	18095715	Oil level	~		
VIN:	TMBKE73T5F9007314	Next Service:	190,797 14115	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		~ · · ·			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	SC W	-0	ls		Р	Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent						Operation V			[
R = rust				TIM	JHIK	Noise	~		
PT = paint def C = crack				+	SC	Clutch			~
P = pin dent	Ho					CV joints	~		
* = decals	sc PK					Wheel bearings	~		
SC = stone chi	ps U	20		100	&	Brakes	V		<u> </u>
W = significant scuffs SC W D P W									
		Noto: com			layed in the diagram		~		
Body Ins	pection Comments	note: son	le délècts à blemisme	es may not be disp	layed in the diagram	Hand Brake		- (
						Tyres (lowest observed tread depth of tyres)			
						Left front	4		mm
						Right front	4		mm
						Left rear	4		mm
Conditions During Body Inspection: Wet						Right rear	4 mm		mm
Under Comiene Ollie der Deue et leur ertien Commente						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Stains on s	seats				Head lights	~		
Carpets	Hole in dri	ivers carpet				Tail lights	~		
Carpets						Indicators	~		
Panels	Drivers pa	nel worn and scr	atched			Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
			**			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
						-			
Inspected by: John Lindsay Date: 21 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: