

## **Basic Vehicle Condition Guide**

Report ID: 18,095,762


Version:

Created: 06 Aug 2018

Make: Model: Suzuki Vitara **Body Style:** SUV Year: 2,016 Registration: KPR7 Reg Expiry: 29 Sep 2018 WoF Expiry: **Odometer: Good No:** 07 Mar 2019 18095762 17,036 Kms VIN: TSMLYD21S00177566 **Next Service: Service History:** 15,000

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Right inner c/v boot leak

| Interior Comments |      |  |  |
|-------------------|------|--|--|
| Seats             | Good |  |  |
| Carpets           | Good |  |  |
| Panels            | Good |  |  |
| Dashboard         | Good |  |  |

**General Comments** 

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Kms: Not Applicable

27 Jun 2018 Inspected by: lan Dunn Date:

Name: .....

|  | Pass                  | Fail | N/A      |  |  |
|--|-----------------------|------|----------|--|--|
| Engine                                       |                       |      |          |  |  |
| Oil level                                    | ~                     |      |          |  |  |
| Smoke & fumes                                | v<br>v                |      |          |  |  |
| Performance                                  | ~                     |      |          |  |  |
| Noise  | ~                     |      |          |  |  |
| Cooling System                               |                       |      |          |  |  |
| Coolant condition                            | ~                     |      |          |  |  |
| Performance                                  | ~                     |      |          |  |  |
| Radiator / Hoses (visual)                    | ~                     |      |          |  |  |
| Transmission                                 |                       |      |          |  |  |
| Operation                                    | ~                     |      |          |  |  |
| Noise  | <b>V</b>              |      |          |  |  |
| Clutch                                       |                       |      | ~        |  |  |
| CV joints                                    | ~                     |      |          |  |  |
| Wheel bearings                               | ~                     |      |          |  |  |
| Brakes                                       |                       |      |          |  |  |
| Performance                                  | ~                     |      |          |  |  |
| Hand Brake                                   | ~                     |      |          |  |  |
| Tyres (lowest observed tread depth of tyres) |                       |      |          |  |  |
| Left front                                   | 4                     | .2   | mm       |  |  |
| Right front                                  | 5.4                   |      | mm       |  |  |
| Left rear                                    | 5.6                   |      | mm       |  |  |
| Right rear                                   | 5.7                   |      | mm       |  |  |
| Spare  |                       | Yes  |          |  |  |
| Suspension                                   |                       |      |          |  |  |
| Suspension performance                       | ~                     |      |          |  |  |
| Steering performance                         | V                     |      |          |  |  |
| Shock absorbers                              | ~                     |      |          |  |  |
| Air Conditioning / Heater                    |                       |      |          |  |  |
| Operation                                    | ~                     |      |          |  |  |
| Electrical / Accessories                     |                       |      |          |  |  |
| Head lights                                  | ~                     |      |          |  |  |
| Tail lights                                  | ~                     |      |          |  |  |
| Indicators                                   | ~                     |      |          |  |  |
| Dashboard warning lights                     | ~                     |      |          |  |  |
| Wipers (front & rear)                        | V<br>V<br>V<br>V<br>V |      |          |  |  |
| Window winder FL                             | ~                     |      |          |  |  |
| Window winder FR                             | ~                     |      |          |  |  |
| Window winder RL                             | ~                     |      |          |  |  |
| Window winder RR                             | ~                     |      |          |  |  |
| Rear view mirrors                            |                       |      |          |  |  |
| Radio (basic test only)                      | ~                     |      |          |  |  |
| CD (basic test only)                         | ~                     |      |          |  |  |
| Number of keys                               | 1                     |      | 1        |  |  |
| Central locking                              | <i>'</i>              |      |          |  |  |
| Remote locking                               | <b>'</b>              |      | <u> </u> |  |  |
| Sat. Nav. (basic test only)                  |                       |      | ~        |  |  |
| Reversing camera                             |                       |      |          |  |  |

Signature: .....