

Report ID: 18,096,390 Version: 1 24 Jun 2018 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,016	Registration:	KDF598	Reg Expiry:	10 Jul 2018	Engine			L
WoF Expiry:		Odometer:	61,445 Kms	Good No:	18096390	Oil level	~		
VIN:	6G1FB5E3XGL245509	Next Service:	75000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechar	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	S D SC			715	HIV	Operation	~		
PT = paint def		r I			70H	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7414	CV joints			~
* = decals	sc 916			Te		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			L
vv = significan	SC		S			Performance	~		
Body Ins	paction Comments	Note: som	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front 7			mm
						Right front	7 mm		mm
						Left rear	6	,	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Compete	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Darkle	Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry									
	-					Remote locking	~		
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Stuart Melbourne Date: 24 Jun 2018									
Date: 24 Juli 2018									

I have read and understood this condition guide.

Name:

Signature: