

Report ID: 18,097,418 Version: 2 Created: 01 Aug 2018

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,003	Registration:	FUT864	Reg Expiry:	30 Aug 2018	Engine		I	
WoF Expiry:	17 Jul 2019	Odometer:	169,410 Kms	Good No:	18097418	Oil level	~		
VIN:	7A8C13J0707100252	Next Service:	179000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	r an additional c	narge.	Coolant condition	~		
	W		DD	W		Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			1
B = rust SSC A A SSC A SSC A A SSC A SSC A A S						Operation	~		
PT = paint def	ect NP				11111	Noise	~		
C = crack					R SC	Clutch			~
P = pin dent	HIP				24114	CV joints	~		
* = decals SC 99						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts SC W S D D W						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
body inspection comments					Tyres (lowest observed tread depth of tyres)				
					Left front 6		5	mm	
						Right front	6 mm		mm
						Left rear	7 mm		mm
Conditions During Body Inspection: Dry					Right rear	4 mm		mm	
						Spare	pare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak Sus						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	hole drive	rs carpet				Tail lights	~		
Carpets		-				Indicators	~		
Panels	scratches	door panels				Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	1	
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking		~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: John Lindsay Date: 01 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: