

Basic Vehicle Condition Guide

Report ID: 18,098,218


Version:

Created: 24 Sep 2018

Make: Model: Hyundai lx35 **Body Style:** SUV Year: Registration: GKB190 Reg Expiry: 2012 30 Aug 2018 WoF Expiry: **Odometer:** 27 Jun 2019 **Good No:** 18098218 140,320 Kms VIN: KMHJU81VSCU529187 **Next Service: Service History:** 150300 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips in the windscreen,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|-------------------------------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | stereo needs a code to work , | | |

General Comments

Stereo needs code to work,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

24 Sep 2018 Inspected by: Donovan Matara Date:

Name:

| | Pass | Fail | N/A | |
|--|--------------|------|----------|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | V V | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | • | | | |
| Coolant condition | ~ | | | |
| Performance | <i>v</i> | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | | 7 | mm | |
| Right front | | 7 | mm | |
| Left rear | | 6 | mm | |
| Right rear | 6 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | 1 | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | \(\times \) | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | <i>'</i> | | | |
| Window winder FL | <i>'</i> | | | |
| Window winder FR | • | | | |
| Window winder RL | v | | | |
| Window winder RR | ' | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ' | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ' | |

Signature: