

Basic Vehicle Condition Guide

Report ID: 18,098,391


Version: 2

Created: 28 Mar 2019

Make: Model: **HSV** Clubsport Holden **Body Style:** Wagon Year: 2010 Registration: LHY250 Reg Expiry: 25 Feb 2019 WoF Expiry: **Odometer: Good No:** 26 Apr 2019 158,510 Kms 18098391 VIN: 6G1EX8EW6AL422508 Next Service: 164000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

28 Mar 2019 Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	5	.5	mm
Right front	5.5		mm
Left rear	5		mm
Right rear	5		mm
Spare		Yes	
Suspension			
Suspension performance	V V		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	/		
Window winder FR	~		
Window winder RL	~		
Window winder RR	\(\times \)		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: