

Basic Vehicle Condition Guide

Report ID: 18,099,231


Version: 2

Created: 23 Aug 2018

Make: Model: Landcruiser Prado **Body Style:** SUV Toyota Year: 2,015 Registration: KZB989 Reg Expiry: 17 Aug 2018 WoF Expiry: **Odometer:** 20 Feb 2019 **Good No:** 18099231 52,092 Kms VIN: JTEBH3FJ80K153969 **Next Service:** 65000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Shock absorber leaking. Oil leak around transfer box. Left side step bent

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	\(\tau \)			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	3.0		mm	
Right front	4.0		mm	
Left rear	5.0		mm	
Right rear	6.0		mm	
Spare	Yes			
Suspension				
Suspension performance	~			
Steering performance	<i>V</i>			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V V V			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	\(\triangle \)			
CD (basic test only)	~			
Number of keys	1	L		
Central locking	·			
Remote locking				
Sat. Nav. (basic test only)	V			
Reversing camera	~			
	<u> </u>			

I have read and understood this condition guide.

Bobby Zhong

Name:

Signature:

09 Jul 2018

Date: