

Report ID: 18,099,539 Version: 1 Created: 05 Aug 2018

Make:	Hyundai	Model:	lx35	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,014	Registration:	HPM208	Reg Expiry:	10 Aug 2018	Engine	11		L	
WoF Expiry:	08 Aug 2018	Odometer:	102,132 Kms	Good No:	18099539	Oil level	~			
VIN:	KMHJU81FMEU96998	Next Service:	114000	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.										
a full mechar	lical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:		-0	LS	500-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission	1 1			
D = dent R = rust	sc			215	HIVS	Operation	~			
PT = paint def	ect NP	r I		$\left[\left(\right) \right]$		Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	LENCE HIS				74 <u>11</u> 4	CV joints	~			
* = decals	SRSC 91			10		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
w = significan	S					Performance	~			
Body Insi	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				
						Left front	eft front 5 r			
						Right front	5	;	mm	
						Left rear	5	5	mm	
Conditions During Body Inspection: Wet						Right rear	5 mm			
wet						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	1			
						Suspension performance	~			
Steering performance							~			
Shock abso							~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Comet	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	Good					Wipers (front & rear)	~			
Dashboa	iru					Window winder FL	~			
	-					Window winder FR	~			
General Comments						Window winder RL	~			
Drive belt p	oulley noisy (cold start)					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			۲	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Xinghui Lin Date: 05 Aug 2018										
Inspected by. Allightrelin Date: US Aug 2018										

I have read and understood this condition guide.

Name:

Signature: