

Basic Vehicle Condition Guide

Report ID: 18,099,784

Version:


Created: 09 Jul 2018

Pass Fail N/A

Make: Model: Hilux **Body Style:** Utility Toyota Year: 2,014 Registration: HNH775 Reg Expiry: 21 Jul 2018 WoF Expiry: **Odometer: Good No:** 22 Jul 2018 18099784 48,956 Kms VIN: MR0EZ12G504014093 **Next Service: Service History:** 55,329 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper different colour

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Underbody surface rust

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Good			

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	\(\triangle \)				
Noise	~				
Cooling System			<u> </u>		
Coolant condition	•/				
Performance	\(\triangle \)				
Radiator / Hoses (visual)	•				
Transmission	•				
Operation	•				
Noise	\(\triangle \)				
Clutch	'				
CV joints			~		
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	9	9	mm		
Right front	9		mm		
Left rear	-		mm		
Right rear			mm		
Spare	Yes				
Suspension					
Suspension performance	~				
Steering performance	<i>y</i>				
Shock absorbers	·				
Air Conditioning / Heater	_				
Operation					
Electrical / Accessories	<i>\</i>				
Licetifear / Accessories					
Head lights					
Tail lights	~				
Indicators	V				
Dashboard warning lights					
Wipers (front & rear)	ν ν				
Window winder FL	~				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)	~				
Number of keys	2	I	1		
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Poversing camera			.,		

I have read and understood this condition guide.

Mathew Varghese

Name:

Signature:

09 Jul 2018

Reversing camera