

I have read and understood this condition guide.

Report ID: 18,100,583 Version: 2 Created: 11 Sep 2018

Signature:

Make:	Volkswagen	Model:	Polo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,003	Registration:	ESH223	Reg Expiry:	28 Jul 2018	Engine		I	L
WoF Expiry:	12 May 2019	Odometer:	152,450 Kms	Good No:	18100583	Oil level	~		
VIN:	WVWZZZ9NZ3D1265	Next Service:	166700	Service History	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	DPT DPT		DPT	Radiator / Hoses (visual)	v		
S = scratch						Transmission			
D = dent R = rust SPT SC S S						Operation 🖌			
PT = paint defect						Noise	~		
C = crack					PT	Clutch	-		~
P = pin dent	HID				74 <u>11</u>	CV joints	~		-
* = decals PT SC PIP						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs PT W S D PT D PT W D						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	oftvre	es)
								mm	
						Right front			 mm
						Left rear	0		mm
Conditions During Rody Inspections						Right rear	-		mm
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Oil leak		•				Suspension performance		~	
Engine check light on						Steering performance	~	•	
EPC light or	1					Shock absorbers	• •		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Electrical / Accessories			
Seats drivers seat hole, stains						Head lights			
Jeals						Tail lights	~		
Carpets	Average						~		
Demolo	Average					Dashboard warning lights	~	~	
Panels						Wipers (front & rear)	~	V	
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	Comments					Window winder RL	~	~	
Central/remote locking faulty						Window winder RR		~	
Left rear door doesn't open Both rear windows faulty						Rear view mirrors	~	V	
Knock front suspension						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			
Road Conditions During Test Drive: Wet						Central locking	1		
Road Con	aitions During Test	Drive:	Wet			Remote locking		レ レ	
Engine Tir	ning Mechanism:	Cambelt	:			Sat. Nav. (basic test only)		•	
Evidence of Cam Belt Replacement: Yes Kms: 109,377									v
				10		Reversing camera			~
Inspected by: John Lindsay Date: 11 Sep 2018									

Name: