

Report ID: 18,101,152 Version: 5 Created: 22 Aug 2018

| Make:   | Chevrolet          | Model:               | Camaro         | Body Style:        | Sports Car   |                             | Pass   | Fail | N/A |
|---|--------------------|----------------------|----------------|--------------------|--------------|-----------------------------|--|------|-----|
| Year:   | 1,995              | <b>Registration:</b> | LNC668         | <b>Reg Expiry:</b> | 21 Feb 2019  | Engine                      | 1  |      |     |
| WoF Expiry:   | 27 Feb 2019        | Odometer:            | 41,604 Kms     | Good No:           | 18101152     | Oil level                   | ~  |      |     |
| VIN:  | 2G1FP22S1S2145414  | Next Service:        | 49255          | Service Histor     | <b>y:</b> No | Smoke & fumes               | ~  |      |     |
|   |                    |                      |                |                    |              | Performance                 | ~  |      |     |
| Note: This report is not a warranty<br>This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or  |                    |                      |                |                    |              | Noise                       | ~  |      |     |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends<br>a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |                    |                      |                |                    |              | Cooling System              |  |      |     |
|   |                    |                      |                |                    |              | Coolant condition           | ~  |      |     |
|   |                    |                      |                |                    |              | Performance                 | ~  |      |     |
| Key:  |                    | -0                   |                | -                  | s            | Radiator / Hoses (visual)   | ~  |      |     |
| S = scratch<br>D = dent   |                    |                      |                |                    |              | Transmission                | 1  |      |     |
| B = rust S A A A A A A A A A A A A A A A A A A  |                    |                      |                |                    |              | Operation                   | ~  |      |     |
| PT = paint defect   |                    |                      |                |                    |              | Noise                       | ~  |      |     |
| C = crack   |                    |                      |                |                    |              | Clutch                      |  |      | ~   |
| P = pin dent  | HE                 |                      |                |                    | 74116        | CV joints                   | ~  |      |     |
| *=decals  |                    |                      |                |                    |              | Wheel bearings              | ~  |      |     |
| SC = stone chips  |                    |                      |                |                    |              | Brakes                      |  |      |     |
| W = significant scuffs W P W  |                    |                      |                |                    |              | Performance                 | ~  |      |     |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram   |                    |                      |                |                    |              | Hand Brake                  | ~  |      |     |
| Body Inspection Comments  |                    |                      |                |                    |              | Tyres (lowest observed trea | Tyres (lowest observed tread depth of tyres) |      |     |
|   |                    |                      |                |                    |              | Left front 7 m              |  |      | mm  |
|   |                    |                      |                |                    |              | Right front                 |  | 7    | mm  |
|   |                    |                      |                |                    |              | Left rear                   |  | 7    | mm  |
| Conditions During Body Inspection: Drv  |                    |                      |                |                    |              | Right rear                  |  | 7    | mm  |
| Conditions During Body Inspection: Dry  |                    |                      |                |                    |              | Spare No                    |  |      |     |
| Under Carriage & Under Bonnet Inspection Comments   |                    |                      |                |                    |              | Suspension                  |  |      |     |
| Underbody   | oxidisation        |                      |                |                    |              | Suspension performance      | ~  |      |     |
|   |                    |                      |                |                    |              | Steering performance        | ~  |      |     |
|   |                    |                      |                |                    |              | Shock absorbers             | ~  |      |     |
|   |                    |                      |                |                    |              | Air Conditioning / Heater   | 1  |      |     |
|   |                    |                      |                |                    |              | Operation 🖌                 |  |      |     |
| Interior Comments   |                    |                      |                |                    |              | Electrical / Accessories    |  |      |     |
| Seats   | Good               |                      |                |                    |              | Head lights                 | ~  |      |     |
| <u> </u>  | Good               |                      |                |                    |              | Tail lights                 | ~  |      |     |
| Carpets   | 0000               |                      |                |                    |              | Indicators                  | ~  |      |     |
| Panels  | Good               |                      |                |                    |              | Dashboard warning lights    | ~  |      |     |
|   | , Good             |                      |                |                    |              | Wipers (front & rear)       | ~  |      |     |
| Dashboa   | rd                 |                      |                |                    |              | Window winder FL            | ~  |      |     |
|   | •                  |                      |                |                    |              | Window winder FR            | ~  |      |     |
| General Comments  |                    |                      |                |                    |              | Window winder RL            |  |      | ~   |
| Drivers door lock sticky  |                    |                      |                |                    |              | Window winder RR            |  |      | ~   |
|   |                    |                      |                |                    |              | Rear view mirrors           | ~  |      |     |
|   |                    |                      |                |                    |              | Radio (basic test only)     | ~  |      |     |
|   |                    |                      |                |                    |              | CD (basic test only)        |  |      | ~   |
|   |                    |                      |                |                    |              | Number of keys              | 2  |      |     |
| Road Conditions During Test Drive: Wet  |                    |                      |                |                    |              | Central locking             |  | ~    |     |
|   | -                  |                      |                |                    |              | Remote locking              |  |      | ~   |
| Engine Timing Mechanism: Timing Chain   |                    |                      |                |                    |              | Sat. Nav. (basic test only) |  |      | ~   |
| Evidence  | of Cam Belt Replac | ement: N             | lot Applicable | Kms:               |              | Reversing camera            |  |      | ~   |
|   |                    |                      |                |                    |              |                             |  |      |     |
| Inspected by: John Lindsay Date: 22 Aug 2018  |                    |                      |                |                    |              |                             |  |      |     |
|   |                    |                      |                |                    |              |                             |  |      |     |

I have read and understood this condition guide.

Name: .....

Signature: .....