

Report ID: 18,101,785 Version: 1 Created: 27 Jun 2018

Make:	Mazda	Model:	Bongo	Body Style:	Van		Pass	Fail	N/A
Year:	2,013	Registration:	bongo	Reg Expiry:	van	Engine			
I	2,013 21 Jun 2019	Odometer:	100,469 Kms		18101785	Oil level	~		
VIN:	7AT0C10WX18203203		110400	Service History		Smoke & fumes	~		
	741001000018205205	HEAT DEI VICE.	110400		• 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:						Performance	~		
S = scratch	R	(0)	<u>Ant</u>	100	~	Radiator / Hoses (visual)	~		
						Transmission			
R = rust	MID				HUY	Operation	~		
PT = paint def	ect					Noise	~		
C = crack	14]]]]]	Clutch	~		
P = pin dent * = decals	dik			SI	副母	CV joints			~
SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Ins	pection Comments	Note: som	ne defects & blemishes	may not be displ	ayed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	e	5	mm
						Right front	6	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL		<u> </u>	~
						Window winder RR		1	~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		<u> </u>
Road Conditions During Test Drive: Wet						Central locking	2 V		
			Wet			Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	•	•							
Inspected by: Bobby Zhong Date: 27 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: