

Report ID: 18,101,958 Version: 2 16 Jul 2018 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2,008	Registration:	ESG279	Reg Expiry:	30 Oct 2018	Engine	I	1	1
WoF Expiry:	20 Apr 2019	Odometer:	139,620 Kms	Good No:	18101958	Oil level	~		
VIN:	MMBJNKB808D03315	Next Service:		Service Histor		Smoke & fumes		~	
						Performance	~	-	
Note: This report is not a warranty This report is a guide only Consideration is made for any and mileage. Darts have not been dismonthed or						Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	harge.	Coolant condition	~		1
		_				Performance	~		
Key:	SD	-0	S SC S	-161-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D=dent S SC						Operation	~		
R = rust PT = paint defect C = crack						Noise	~		
						Clutch	~		
P = pin dent						CV joints	-		
* = decals SC PIP							~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs S S S S S						Brakes			
		N				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		6 .	Ļ
High mount brake light insecure						Tyres (lowest observed tread depth of tyres)			-
Stone chip on front windscreen						Left front	6	6 mm	
						Right front	6	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	4	1	mm
						Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Underbody	surface rust					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	_		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		1
General Comments					Window winder RL	~		1	
Engine noisy and smoke						Window winder RR	V		1
						Rear view mirrors	~		1
						Radio (basic test only)	~		+
						CD (basic test only)	~		+
						Number of keys	1		1
Road Car	ditions During Test	Drivo:				Central locking	· ·		1
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
	of Cam Belt Replac		lot Applicable	Kms:		Reversing camera			~
	•	•	- 1-1						
Inspected by: Xinghui Lin						Date: 16 Jul 201	8		
I have read	and understood th	is condition o	juide. Name: .			Signature:			