

Basic Vehicle Condition Guide

Report ID: 18,102,283


Version:

Created: 17 Jul 2018

Make: Model: Hyundai lx35 **Body Style:** SUV Year: 2,015 Registration: HZQ806 Reg Expiry: 26 Mar 2019 WoF Expiry: **Odometer: Good No:** 23 Mar 2019 18102283 39,662 Kms VIN: KMHJT81FMFU060645 **Next Service: Service History:** 52000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Law Date: 17 Jul 2018

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	V V			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	,	5	mm	
Right front		5	mm	
Left rear		7	mm	
Right rear	7		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater		1		
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	V V V V V			
Window winder FR				
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	\(\times \)			
Radio (basic test only)				
CD (basic test only)	~			
Number of keys 2				
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera	'			

Signature: