

Report ID: 18,102,352 Version: 2 Created: 04 Sep 2018

Make:	Ford	Model:	Ranger	Body Style:	Utility	1[		Pass	Fail	N/A	
Year:	2,014 <b>Registration:</b> HSF56 <b>Reg Expiry:</b> 29 Jul 2018					Engine					
WoF Expiry:	29 Nov 2018	Odometer:	89,269 Kms	Good No:	18102352		Oil level	~			
VIN:	MNAUMFF50EW3060	Next Service:	85,000	Service Histor	<b>y:</b> No		Smoke & fumes	~			
						il	Performance		~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
							Coolant condition	~			
	P SC				S	1	Performance	~			
							Radiator / Hoses (visual)	~			
S = scratch D = dent							Transmission		1	1	
							Operation	~			
PT = paint defect							Noise	~			
C = crack							Clutch			~	
P = pin dent							CV joints	~			
e decais							Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes					
W = significant scutts P D W							Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Hand Brake	~			
Tuff deck poor fit							Tyres (lowest observed tread depth of tyres)				
Dents scuffs on inner door sills							Left front 7			mm	
							Right front	-	7	mm	
						] [	Left rear	:	2	mm	
Conditions During Body Inspection: Wet						1[	Right rear		2	mm	
						-	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
Engine oil leak Bonnet cable handle insecure							Suspension performance	~			
							Steering performance	>			
							Shock absorbers	~			
							Air Conditioning / Heater				
						i	Operation	~			
Interior Comments							Electrical / Accessories				
Seats	Good						Head lights	~			
Carpets	Good						Tail lights	~			
							Indicators	~			
Panels	Average						Dashboard warning lights		~		
Dashboa	Good Good				Wipers (front & rear)	~					
							Window winder FL	~			
						Ī	Window winder FR	~			
General Comments							Window winder RL	~			
Engine MIL	UII						Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						ן <u>י</u>	Number of keys	1			
Road Conditions During Test Drive: Wet							Central locking	~			
						Ī	Remote locking	~			
Engine Timing Mechanism: Timing Chain							Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera			~	
Inspected by: Mathew Varghese Date: 04 Sep 2018											

I have read and understood this condition guide.

Name: .....

Signature: .....