

Report ID: 18,102,692 Version: 1 Created: 04 Jul 2018

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2,012	Registration:	GMU526	Reg Expiry:	30 Nov 2018	Engine	1		1
WoF Expiry:	12 Jul 2019	Odometer:	133,440 Kms	Good No:	18102692	Oil level	~		
VIN:	KMHSH81XSCU90482	Next Service:	135000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
					S P SC	Performance	r		
Key:	S SC	-0	S P SC S P SC		SPSC	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack						Transmission			
						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	V		
* = decals SC 99 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S D SC						Performance	~		
Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments Minor stone ships in the winderscon						Tyres (lowest observed tread depth of tyres)			es)
Minor stone chips in the windscreen ,						Left front 7 mr			mm
						Right front		7	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	V		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
<u></u>	Average					Tail lights	~		
Carpets	//veruge					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1				·	Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
						-	-		
Inspected by: Donovan Matara Date: 04 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: