

Report ID: 18,102,895 Version: 2 23 Nov 2018 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2016	Registration:	KDD95	Reg Expiry:	30 Jun 2018	Engine			1
WoF Expiry:	23 Nov 2019	Odometer:	51,324 Kms	Good No:	18102895	Oil level	~		
VIN:	6G1FB5E34GL245554	Next Service:	60000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		<u> </u>
	port is not a warranty	avation is made	for one and miles a	Dauta hava nat	heen discontinuing or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch	RE	A U			Ton .	Transmission			
D = dent	- HE			ZIS		Operation	~		
R = rust PT = paint def				\prod	JUIL	Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	616			- NL		Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significan	t scuffs	$- \emptyset$		JYW		Performance	~		
		Note: son	ne defects & blemishes	s mav not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments				,	Tyres (lowest observed tread	•	oftvre	 >s)
						Left front 7.0 mm			
						Right front		.0	mm
						Left rear			mm
						Right rear	5.5		mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	t surface rust under carr	•				Suspension performance	~		
j						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater	•		<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Jeals						Tail lights			<u> </u>
Carpets	Good						レ レ		<u> </u>
Dev. 1	Good					Dashboard warning lights			<u> </u>
Panels						Wipers (front & rear)	v		<u> </u>
Dashboa	rd Good					Window winder FL	~ ~		<u> </u>
						Window winder FL Window winder FR			┼──
General (<u>Comments</u>					Window winder FR Window winder RL	v		<u> </u>
							~		├──
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		──
						Radio (basic test only)	~		
						CD (basic test only)	2		~
			_			Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Enaine Tir	ming Mechanism:	Timing	Chain			Remote locking	~		<u> </u>
-	of Cam Belt Replac	_	lot Applicable	Kms:		Sat. Nav. (basic test only)			~
	o. cam bert hepiac			11113.		Reversing camera	~		
Inspected by: Eddie Marsters Date: 24 Aug 2018									

I have read and understood this condition guide.

Name: