

Report ID: 18,194,152 Version: 1 26 Jun 2018 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2,012	Registration:	GKQ799	Reg Expiry:	24 Oct 2018	Engine	I		L
WoF Expiry:	09 Apr 2019	Odometer:	186,329 Kms	Good No:	18194152	Oil level	~		
VIN:	MNAUMFF50CW1162	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	r		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
			S SC S		S	Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			20	E S	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch	~		
P = pin dent	PSC DE				74II <u>L</u>	CV joints	~		
* = decals		10		10	ED SP	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
- Significan	S	C	S S D		S D	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
FR door glass run channel needs attention						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front 7			mm
						Right front	5	7	mm
						Left rear	,	7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil l	eak					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		L
						Operation	~		
Interior Comments						Electrical / Accessories	1		
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
-						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
		_							
Inspected by: Mathew Varghese Date: 26 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: