

Report ID: 18,195,596


Version:

24 Jul 2018 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Wagon
Year:	2,006	Registration:		Reg Expiry:	
WoF Expiry:	22 Jun 2019	Odometer:	97,403 Kms	Good No:	18195596
VIN:	7AT0C139X18401406	Next Service:	107000	Service History	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

27 Jun 2018 Inspected by: **Bobby Zhong** Date:

	Pass	Fail	N/A				
Engine		1					
Oil level	~						
Smoke & fumes	\(\times \)						
Performance	~						
Noise	~						
Cooling System			1				
Coolant condition	~						
Performance	V						
Radiator / Hoses (visual)	~						
Transmission							
Operation	~						
Noise	~						
Clutch			~				
CV joints	~						
Wheel bearings	~						
Brakes							
Performance	~						
Hand Brake	~						
Tyres (lowest observed tread depth of tyres)							
Left front	5	.0	mm				
Right front	5	.0	mm				
Left rear	3	.0	mm				
Right rear	4	.0	mm				
Spare		Yes					
Suspension							
Suspension performance	~						
Steering performance	~						
Shock absorbers	~						
Air Conditioning / Heater		ı					
Operation	~						
Electrical / Accessories		1					
Head lights	~						
Tail lights	~						
Indicators	~						
Dashboard warning lights	\(\times \) \(\t						
Wipers (front & rear)	~						
Window winder FL	~						
Window winder FR	~						
Window winder RL	~						
Window winder RR	~						
Rear view mirrors	V						
Radio (basic test only)	~						
CD (basic test only)	~						
Number of keys	1						
Central locking	~						
Remote locking	~						
Sat. Nav. (basic test only)			~				
Reversing camera			'				

I have read and understood this condition guide.

Name:

Signature: