

Report ID: 18,195,971 Version: 1 25 Jun 2018 Created:

| Make: | Chrysler | Model: | Neon | Body Style: | Sedan | | Pass | Fail | N/A |
|--|---------------------------|---------------------|---------------------|----------------|-------------|--|------|------|----------|
| Year: | 2,002 | Registration: | ANK408 | Reg Expiry: | 21 Jul 2018 | Engine | | | L |
| WoF Expiry: | 20 Dec 2018 | Odometer: | 269,061 Kms | Good No: | 18195971 | Oil level | ~ | | |
| VIN: | 1C3EVM6C8YD844182 | | , | Service Histor | | Smoke & fumes | ~ | | |
| | | | 211301 | | | Performance | ~ | | |
| Note: This report is not a warranty | | | | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | | | |
| Key: | S SC | -0 | S PT P SC S PT P S | | s | | ~ | | |
| S = scratch | | | | | | Radiator / Hoses (visual) Transmission | ~ | | |
| D = dent | s sc ale | | | 1 - L | HID | | | | |
| R = rust | | | | 10 | | Operation | ~ | | |
| PT = paint defe | ect M | | | $\square \cup$ | S PT | Noise | ~ | | <u> </u> |
| C = crack P = pin dent | IIIo | | | - | | Clutch | ~ | | |
| * = decals | s sc db | | | | EL SPT | CV joints | ~ | | |
| SC = stone chips | | | | | | Wheel bearings | ~ | | |
| W = significant scuffs | | | | | | Brakes | | | |
| | S SC S | | S D S P SC | S | | Performance | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | ~ | | |
| Flaky clear coat on some parts of the car,aerial broken , | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 2 mm | | mm |
| | | | | | | Right front | | 2 | mm |
| | | | | | | Left rear | 6 | 5 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 6 | 5 | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | Suspension | | | | |
| Minor surfa | ce rust,minor oil leak,wa | ater in radiator lo | ooks rusty colour , | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | - | | |
| | | | | | | Operation | | ~ | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | wear and t | ear, | | | | Head lights | ~ | | |
| Comoto | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | Average | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ra | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| <u>General C</u> | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Unknown | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| | | | | | | | 1 | | |
| Inspected by: Donovan Matara Date: 25 Jun 2018 | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |