

Report ID: 5,548 Version: 1 Created: 13 Jul 2018

Make:	Volkswagen	Model:	Т5	Body Style:	Van			Pass	Fail	N/A	
Year:	2,009	Registration: FFP169 Reg Expiry: 01 Jul 2018			Engine				I		
WoF Expiry:		Odometer: 165,190 Kms Good No: 18197375			Oil leve	2	~				
VIN:	WV1ZZZ7HZ9H10070	Next Service:	175,000	Service Histor	y: No	Smoke	& fumes	~			
						Perform	nance	~			
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismontled or	Noise		~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							System				
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolan	t condition	~			
						Perform	nance	~			
Key:		-0		-01-		Radiato	or / Hoses (visual)	r			
S = scratch D = dent						Transmi	ssion	1			
B = rust S A A A A A A A A A A A A A A A A A A						Operat	ion	~			
PT = paint def	ect NP				70111	Noise		~			
C = crack						Clutch		~			
P = pin dent	HIP				74116	CV join	ts	~			
* = decals	- Alt	10		10		Wheel	bearings	~			
SC = stone chips W = significant scuffs						Brakes					
						Performance		~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand B	Brake	~			
						Tyres (lowest observed tread depth of tyres)					
						Left front		4	4 mn		
						Right fr	ront	4	4	mm	
						Left rea	ar	4	1	mm	
Conditions During Body Inspection: Dry						Right re	Right rear		4	mm	
							Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspens	ion				
						Suspen	sion performance	~			
						Steerin	g performance	~			
							absorbers	~			
						Air Conditioning / Heater					
Interior Commonts							ion	~			
Interior Comments						Electrical / Accessories					
Seats	Average	Average				Head li	-	~			
Carpets	Average					Tail ligh		~			
	Good			Indicat		~					
Panels	Good	Good					bard warning lights	~			
Dashboa	rd Good	Good					(front & rear)	~			
	-						w winder FL	~			
General Comments							w winder FR	~			
							w winder RL			~	
							w winder RR			~	
							ew mirrors	~			
							basic test only)	~			
							sic test only)	~			
							er of keys	1			
Road Conditions During Test Drive: Dry							l locking	~			
Engine Timing Mechanism: Cambelt							e locking	~			
Evidence of Cam Belt Replacement: No Kms:							v. (basic test only)			v	
			···			Reversi	ing camera			~	
Inspecte	d by: Scott						Date: 05 Jul 201	8			

I have read and understood this condition guide.

Name:

Signature: